

OWNER NOTIFICATION PROGRAM	99B29
-----------------------------------	--------------

Certain 1996 and 1997 model year Mustang, Thunderbird, Cougar, and 1997 F-Series vehicles equipped with 3.8L or 4.2L engines - Replacement of Engine Front Cover Gasket

2 Original - December, 1999

2 Front Cover - January, 2000

Front Cover Assembly Breaking on 3.8L & 4.2L Engines Repaired Under Owner Notification Program (ONP) 99B29

2 Revised Labor Times; Customer Refunds - February, 2000

Owner Notification Program (ONP) 99B29: 1. Revised Labor Time for 4.2L F-Series Repairs.
2. Refund Customers May Need a New Front Cover Gasket.

2 New Front Cover & Engine Availability

1. New Front Cover Assembly Without Oil Pump Released for 3.8L & 4.2L Engines 2.
Availability of Engine Assemblies

2 Supplement #1 - April, 2000

Certain 1996 and 1997 model year Mustang, Thunderbird, Cougar, and 1997 F-Series vehicles equipped with 3.8L or 4.2L engines - Replacement of Engine Front Cover Gasket
