

TSB 98-7-4

FORD:

1984-94 TEMPO
1984-97 THUNDERBIRD
1984-98 CROWN VICTORIA, ESCORT, MUSTANG
1986-98 TAURUS
1989-97 PROBE
1994-97 ASPIRE
1995-98 CONTOUR

LINCOLN-MERCURY:

1984-94 TOPAZ
1984-97 COUGAR
1984-98 CONTINENTAL, GRAND MARQUIS, TOWN CAR
1986-98 SABLE
1989-98 TRACER
1993-98 MARK VIII
1995-98 MYSTIQUE

LIGHT TRUCK:

1983-98 RANGER
1984-96 BRONCO
1984-98 ECONOLINE, F-150, F-250 HD, F-250 LD
1984-99 SUPER DUTY F SERIES
1986-97 AEROSTAR
1991-98 EXPLORER
1993-98 VILLAGER
1996-98 WINDSTAR
1997-98 EXPEDITION, MOUNTAINEER
1998 NAVIGATOR

ISSUE:

A new Silicone Gasket And Sealant (F7AZ-19554-EA) material is now available for routine engine service or repair of engine oil leaks.

ACTION:

Use the new Silicone Gasket And Sealant for servicing:

- Oil pan gaskets and T-joints
- Intake end seals
- Overhead cam caps
- Valve and timing covers
- Bearing split lines
- Side cover plates
- Rear oil seals

The new sealant has better adhesion, flexibility for moving/vibrating joints, resistance to fluids, and is easier to dispense.

NOTE:

THIS MATERIAL IS NOT A DIRECT REPLACEMENT FOR A SILICONE RUBBER, GRAPHITE,
OR OTHER TYPE OF PRE-FORMED GASKET.

ÚAAZ		3
3	PART NUMBER	3
	PART NAME	3
3	F7AZ-1954-EA	3
	3 Silicone Gasket And Sealant	3
AAAU		